

Dallas - SWAAM
5040 Addison Circle
Addison, TX75001
Phone: (972) 788-0026

Property Condition Report



Case Number: 492-656498

Full Address: 625 DONLEY DR
EULESS, TX 76039

Inspection Date: 01/20/2010

Revision Date: 02/12/2010

Inspection Type: Property Condition Report

NOTICE TO ALL PROSPECTIVE PURCHASERS: Pursuant to section 5.3.4 of HUD RFP: R-OPC-22505, you are hereby notified that the contents of this inspection report are for information only and do not express or imply any guarantee or warranty or representation of property condition.

Table Of Contents

| | |
|---|----|
| 1 INSPECTION REQUIREMENTS | 3 |
| 1.1. Exclusions of Inspection | 3 |
| 1.2. Exclusions and Limitations | 3 |
| 2 REPORT SUMMARY | 4 |
| 3 DIRECTIONS TIPS TO PROPERTY | 5 |
| 4 PROPERTY INFORMATION | 5 |
| 5 ADDITIONAL COMMENTS | 5 |
| 6 STRUCTURAL COMPONENTS | 6 |
| 6.1 General Structural Information | 6 |
| 6.2 Structural CheckPoints | 6 |
| 6.3 Structural Comments | 6 |
| 7 EXTERIOR OF STRUCTURE | 7 |
| 7.1 General Exterior Information | 7 |
| 7.2 Exterior CheckPoints | 7 |
| 7.3 Exterior Comments | 8 |
| 8 ROOFING | 9 |
| 8.1 General Roof Information | 9 |
| 8.2 Roofing CheckPoints | 9 |
| 8.3 Roofing Comments | 9 |
| 9 PLUMBING | 10 |
| 9.1 General Plumbing Information | 10 |
| 9.2 Plumbing CheckPoints | 10 |
| 9.3 Plumbing System Comments | 11 |
| 10 ELECTRICAL | 12 |
| 10.1 General Electrical Information | 12 |
| 10.2 Electrical CheckPoints | 12 |
| 10.3 Electrical System Comments | 12 |
| 11 HVAC (Heating Ventilation, Air Conditioning) | 13 |
| 11.1 General HVAC Information | 13 |
| 11.2 HVAC CheckPoints | 13 |
| 11.3 HVAC Comments | 14 |
| 12 INTERIOR | 15 |
| 12.1 General Interior Information | 15 |
| 12.2 Interior CheckPoints | 15 |
| 12.3 Interior Comments | 15 |
| 13 APPLIANCES | 16 |
| 13.1 General Appliance Information | 16 |
| 13.2 Appliance CheckPoints | 16 |
| 13.3 Appliance Comments | 16 |
| 14 HOA INFORMATION | 17 |
| 15 CODE VIOLATIONS | 17 |

| | |
|---|----|
| 16 PENDING LITIGATION | 17 |
| 17 DEMO ORDERS | 17 |
| 18 MOLD DISCLOSURE | 18 |
| 19 ENVIRONMENTAL ISSUES | 19 |
| 19.1. Environmental Compliance Record | 19 |



1 INSPECTION REQUIREMENTS

STRUCTURAL COMPONENTS including foundation, floors, walls, columns, ceilings, and roofs.

EXTERIOR OF STRUCTURE including wall claddings, entryway doors, decks, steps, eaves, driveways, windows, patios, pools/spas, lawns, landscape, retaining walls, sheds/outbuildings, and fences.

ROOFING including roof coverings, roof drainage systems, flashing, skylights, and chimneys.

PLUMBING including interior water supply and distribution system, interior waste drains and vent system, hot water system, fuel storage and distribution system, and sump pump.

ELECTRICAL including service entrance conductors, service equipment, main distribution panels, voltage ratings, a representative number of installed ceiling fans, lighting fixtures, switches and receptacles, ground fault circuit interrupters, and smoke detectors.

HVAC (Heating Ventilation, Air Conditioning) including permanently installed heating system and its controls, chimneys, heat distribution system, including fans, pumps, and ducts, and automatic safety controls.

Normal operating control of the central air conditioning system and the distribution system.

Insulation vapor barriers, ventilation of attic and foundation, kitchen, bathroom and laundry venting systems, and the operation of any readily accessible attic ventilation fan when temperature permits.**INTERIOR** including walls, ceilings, floors, steps, cabinets, doors, windows, etc.

BUILT-IN KITCHEN APPLIANCES including the observation and operation of dishwasher, range, trash compactor, garbage disposal, ventilation equipment, permanently installed oven and microwave oven.

1.1. Exclusions of Inspection

1.2. Exclusions and Limitations

This inspection is limited to visual observations of apparent conditions existing at the time of the inspection only. This inspection is not intended to provide the purchaser with information regarding the advisability of this purchase, the market value of the property, the compliance or non-compliance with codes, ordinances and statutes, the suitability of this property for specialized use, the life expectancy of any component or system in the property, the presence or absence of pests or insects, or cosmetic or underground items or items that are not permanently installed. This inspection report does not address and it not intended to address the possible presence of any danger from any potentially harmful substance and environmental hazards, including but not limited to radon gas, lead paint, asbestos, urea formaldehyde (UFFI), toxic or chemical analysis, airborne hazards, mold, polluted water, or underground oil tanks

2 REPORT SUMMARY

This summary is provided to highlight those findings that we believe are for information, significant in nature or which appear to be in immediate need of repair or a safety concern.

This inspection is visual only and performed only in areas that were readily accessible at the time of inspection. No dismantling of building components or systems, no destructive or environmental testing, no engineering functions, and no code compliance inspections were performed at the time of the inspection. The findings were as follows:

A Structural Comments

- Ceilings - CRACKS, WATER STAINS
- Cracks - CRACKS PRESENT
- Floor - DAMAGE PRESENT
- Structural - CRACKS, NEED ENGINEER REPORT
- Walls - CRACKS
- General Structural Comments - FOUNDATION INSPECTION RECOMMENDED.

B Exterior of Structure

- Eaves - PEELING.
- Fencing/Gates - DAMAGE PRESENT
- Garage Door - PEELING.
- Porches - MISSING PILLAR.
- Sheds/Outbuildings - UNFINISHED STORAGE BUILDING, FRAME ONLY
- Siding Conditions - CRACKS, HOLES, PEELING AT SIDING AND TRIM.

C Roofing

- Soffits/Fascias - DAMAGE PRESENT. PEELING.

D Plumbing

- Connections - pressure tested at 40 psi, dropped to 28 psi@ 20 minutes
- Kitchen Sink - MISSING FAUCET
- General Plumbing System Comments - pressure tested at 40 psi, dropped to 28 psi @ 20 minutes

E Electrical

• General Electrical System Comments - ALL APPLIANCES WERE POWERED THROUGH THE USE OF A GENERATOR FOR TESTING.

F HVAC - Heating, Ventilation, Air Conditioning

• General HVAC Comments - ALL APPLIANCES WERE POWERED THROUGH THE USE OF A GENERATOR FOR TESTING.

G Interior

- Ceilings - CRACKS, WATER STAINS AT HALLWAY
- Door Hardware - SOME MISSING AND DAMAGED.
- Floors - DAMAGE PRESENT, CARPET REMOVED FROM FRONT BR, CARPET TORN AND VINYL DAMAGED
- Walls - DAMAGE PRESENT, CRACKS
- General Interior Comments - 3 BED, 2 BATH

H Appliances

• General Appliance Comments - ALL APPLIANCES WERE POWERED THROUGH THE USE OF A GENERATOR FOR TESTING.

3 DIRECTIONS TIPS TO PROPERTY
55C FW MAPSCO

4 PROPERTY INFORMATION

| | | | |
|--|--------------------|--------------------|---------------|
| Access To Property: | HUD KEY | Address: | 625 DONLEY DR |
| Occupied: | N | City: | EULESS |
| Square Footage(to be verified): | 1523 Per Appraisal | Zip Code: | 76039 |
| Number Of Baths: | 2.00 | State: | TX |
| Structure Age(to be verified): | 46 | County: | TARRANT |
| Subdivision: | MIDWAY PARK ADDN | Lot Number: | 27 |
| Square/Block: | 30 | Section: | |

Plat:

Metes and Bounds Description: LOT 27, BLOCK 30, MIDWAY PARK ADDITION TO THE CITY OF EULESS, TARRANT COUNTY, TEXAS

Status of Utilities:

| | | | | | |
|----------------------|---|----------------|---|---------------|---|
| Electric: | N | Gas: | N | Water: | N |
| See 10.3, 11.3, 13.3 | | See 11.3, 13.3 | | See 9.3 | |

5 ADDITIONAL COMMENTS

| | | | |
|-------------------------------------|--------|----------------------|----------|
| Power Company: | ONCOR | Meter Number: | 46729177 |
| Gas Company: | ATMOS | Meter Number: | L410761 |
| Water Company: | EULESS | | |
| HOA Transferable Warranties: | NA | | |

6 STRUCTURAL COMPONENTS

This portion of the inspection covers general structural component checkpoints of the subject property such as Foundation, floors, walls, columns, ceilings, basements, etc.

6.1 General Structural Information

Access Method: HUD KEY

Foundation Type: SLAB

Basement Type: NA

6.2 Structural CheckPoints

| Checkpoints | Rating * | Comments |
|----------------------|----------|------------------------------|
| Basement Floor | NA | |
| Beam Supports | S | |
| Ceilings | M | CRACKS, WATER STAINS |
| Cracks | M | CRACKS PRESENT |
| Crawlspace Door | S | |
| Floor | M | DAMAGE PRESENT |
| Footing Drain | NA | |
| Ground Grade | S | |
| Insulation | S | |
| Joists | S | |
| Sill Plate | S | |
| Structural | M | CRACKS, NEED ENGINEER REPORT |
| Sub-Flooring | S | |
| Walls | M | CRACKS |
| Wood-Ground Distance | S | |

*Ratings: S=Satisfactory U=Unsatisfactory M=Marginal MG=Missing NA=Not Applicable NV=Not Visible

6.3 Structural Comments

FOUNDATION INSPECTION RECOMMENDED.

7 EXTERIOR OF STRUCTURE

This portion of the inspection covers general exterior checkpoints of the subject property structure such as wall claddings, entryway doors, decks, steps, eaves, driveways, windows, patios, pools/spas, lawns, landscape, retaining walls, sheds/outbuildings, fences, etc.

7.1 General Exterior Information

Exterior Siding Type: BRICK AND WOOD

Lot Size:

Temperature: 65

Wall Structure: WOOD

Weather Conditions: CLEAR

7.2 Exterior CheckPoints

| Checkpoints | Rating * | Comments |
|--------------------|----------|--|
| Balconies | NA | |
| Carpports | NA | |
| Debris | NA | |
| Decks | NA | |
| Driveway | S | |
| Eaves | M | PEELING. |
| Entry Locks | S | |
| Exterior Doors | S | |
| Fencing/Gates | M | DAMAGE PRESENT |
| Garage Door | M | PEELING. |
| Garage Door Opener | S | |
| Landscape | M | |
| Lawn Care | S | |
| Leaf Removal | S | |
| Patio | NA | |
| Pool/Spa | NA | |
| Porches | M | MISSING PILLAR. |
| Railings | NA | |
| Retaining Walls | NA | |
| Sheds/Outbuildings | M | UNFINISHED STORAGE BUILDING, FRAME ONLY |
| Sidewalks | S | |
| Siding Conditions | M | CRACKS, HOLES, PEELING AT SIDING AND TRIM. |
| Snow Removal | NA | |
| | | |

| Checkpoints | Rating * | Comments |
|----------------------|----------|----------|
| Steps | S | |
| Storm/Screen Doors | NA | |
| Storm/Screen Windows | S | |
| Windows | S | |

*Ratings: S=Satisfactory U=Unsatisfactory M=Marginal MG=Missing NA=Not Applicable NV=Not Visible

7.3 Exterior Comments

8 ROOFING

This portion of the inspection covers general exterior roofing component checkpoints of the subject properly such as roof coverings (shingles, flashing, skylights, chimneys, etc.), structural elements of the roof (trusses, rafters, ceiling foists, etc.), roof drainage systems, etc.

8.1 General Roof Information

Attic Type: WALK
 Gutter Type: METAL
 Method to Observe Attic: STAIRS
 Method Used to Observe Roof: VISUAL
 Number of Layers: 1
 Roof Type: GABLE
 Roofing Material: COMPOSITION

8.2 Roofing CheckPoints

| Checkpoints | Rating * | Comments |
|----------------------|----------|--------------------------|
| Shingle Condition | M | |
| Flashing/Joints | S | |
| Soffits/Fascias | M | DAMAGE PRESENT. PEELING. |
| Skylights | NA | |
| Vent Pipes | S | |
| Chimney | S | |
| Gutters | S | |
| Downspouts | S | |
| Attic Ventilation | S | |
| Attic Water | NA | |
| Attic Insulations | S | |
| Structural Condition | S | |
| Sheathing Condition | S | |
| Truss | S | |
| Roof Exhaust Fan(s) | S | |

*Ratings: S=Satisfactory U=Unsatisfactory M=Marginal MG=Missing NA=Not Applicable NV=Not Visible

8.3 Roofing Comments

9 PLUMBING

This portion of the inspection covers general plumbing checkpoints of the subject property such as interior water supply and distribution system, interior waste drains and vent system, hot water system, fuel storage and distribution system, and sump pump.

9.1 General Plumbing Information

Waste Disposal: SEWER
Waste Piping: PLASTIC
Water Heater Capacity: 30 GAL
Water Heater Manufacturer: SEARS
Water Heater Model Number: 153336210
Water Piping: COPPER
Water Supply: COPPER

9.2 Plumbing CheckPoints

| Checkpoints | Rating * | Comments |
|---------------------------|----------|--|
| Bar Sink | NA | |
| Bath Fixtures | S | |
| Connections | M | pressure tested at 40 psi, dropped to 28 psi@ 20 minutes |
| Hot Tub/Spa | NA | |
| Interior Vent | S | |
| Kitchen Sink | M | MISSING FAUCET |
| Laundry Tub | NA | |
| Main Shut off | S | |
| Pressure Relief Valve | S | |
| Pressure Tank | NA | |
| Septic Location/Condition | NA | |
| Septic System | NA | |
| Sewer Drainage | S | |
| Shower Pan | S | |
| Sprinkler System | NA | |
| Storage Tanks | NA | |
| Vent System | S | |
| Water Filter | NA | |
| Water Heaters | S | |
| Water Meter | S | |
| Water Softener | NA | |
| | | |

| Checkpoints | Rating * | Comments |
|---------------------|----------|----------|
| Water Supply | S | |
| Well | NA | |
| Well Location | NA | |
| Well Pump/Sump Pump | NA | |

*Ratings: S=Satisfactory U=Unsatisfactory M=Marginal MG=Missing NA=Not Applicable NV=Not Visible

9.3 Plumbing System Comments

pressure tested at 40 psi, dropped to 28 psi@ 20 minutes

10 ELECTRICAL

This portion of the inspection covers general electrical checkpoints of the subject property such as service entrance conductors, service equipment, main distribution panels, voltage ratings, a representative number of installed ceiling fans, lighting fixtures, switches and receptacles, ground fault circuit interrupters, smoke detectors, etc.

10.1 General Electrical Information

Additional Space Available: UNKNOWN
Box Location: GARAGE
Capacity: NA
Conductor Type: NV
General Wiring: NV
Number of Disconnects: 10
Panel Manufacturer: NA
Panel Type: BREAKER
Wiring:

10.2 Electrical CheckPoints

| Checkpoints | Rating * | Comments |
|---------------------|----------|----------|
| Appliance Wiring | S | |
| Bath GFCI | S | |
| Breaker Condition | S | |
| Exterior GFCI | S | |
| Exterior Wiring | S | |
| Ground Bonding | NA | |
| HVAC Wiring | S | |
| Interior Wiring | S | |
| Kitchen GFCI | S | |
| Lighting Fixtures | S | |
| Panel Box | S | |
| Receptacle Location | S | |
| Service Attach | S | |
| Service Meter | S | |
| Sub Panel Box | NA | |

*Ratings: S=Satisfactory U=Unsatisfactory M=Marginal MG=Missing NA=Not Applicable NV=Not Visible

10.3 Electrical System Comments

ALL APPLIANCES WERE POWERED THROUGH THE USE OF A GENERATOR FOR TESTING.

11 HVAC (Heating Ventilation, Air Conditioning)

This portion of the inspection covers general HVAC checkpoints of the subject property such as permanently installed heating system and its controls, chimneys, heat distribution system, including fans, pumps, and ducts, and automatic safety controls. Normal operating control of the central air conditioning system and the distribution system, etc. Insulation vapor barriers, ventilation of attic and foundation, kitchen, bathroom and laundry venting systems, and the operation of any readily accessible attic ventilation fan when temperature permits etc.

11.1 General HVAC Information

Inside Unit Brand: WEATHERKING
Inside Unit Model Number: NV
Inside Unit Type: GAS FURNACE
Outside Unit Brand: RHEEM
Outside Unit Model Number: TF43037JAZ
Outside Unit Type: CONDENSER

11.2 HVAC CheckPoints

| Checkpoints | Rating * | Comments |
|-------------------|----------|----------|
| Air Conditioning | S | |
| Boiler | NA | |
| Coil | S | |
| Coil Fins | S | |
| Condensation Pipe | S | |
| Controls | S | |
| Draft Device | S | |
| Duct Work | S | |
| Electric Heat | S | |
| Evaporator | S | |
| Fans | S | |
| Filters | M | |
| Fireplace | S | |
| Flu Pipes | S | |
| Furnace | S | |
| Gas Lines | S | |
| Heat Exchanger | S | |
| Heat Pump | S | |
| Inside Fan Motor | NV | |
| Oil Tank | NA | |
| | | |

| Checkpoints | Rating * | Comments |
|-----------------------|----------|----------|
| Oil Tank Vent | NA | |
| Refrigerant Line | S | |
| Supply Returns | S | |
| Temperature Drop Test | NA | |
| Thermostat | S | |
| Vapor Barrier | NV | |
| Ventilation | S | |

*Ratings: S=Satisfactory U=Unsatisfactory M=Marginal MG=Missing NA=Not Applicable NV=Not Visible

11.3 HVAC Comments

ALL APPLIANCES WERE POWERED THROUGH THE USE OF A GENERATOR FOR TESTING.

12 INTERIOR

This interior portion of the inspection covers checkpoints involving the interior walls, ceilings, floors, steps, cabinets, doors, and windows.

12.1 General Interior Information

There are no general information points in this section

12.2 Interior CheckPoints

| Checkpoints | Rating * | Comments |
|---------------|----------|---|
| Cabinets | S | |
| Ceilings | M | CRACKS, WATER STAINS AT HALLWAY |
| Closets | S | |
| Countertops | S | |
| Debris | NA | |
| Detectors | S | |
| Door Hardware | U | SOME MISSING AND DAMAGED. |
| Doors | S | |
| Dryer Vent | S | |
| Floors | M | DAMAGE PRESENT, CARPET REMOVED FROM FRONT BR, CARPET TORN AND VINYL DAMAGED |
| Mold | NA | |
| Railings | NA | |
| Stairwells | NA | |
| Steps | NA | |
| Walls | M | DAMAGE PRESENT, CRACKS |
| Windows | S | |

*Ratings: S=Satisfactory U=Unsatisfactory M=Marginal MG=Missing NA=Not Applicable NV=Not Visible

12.3 Interior Comments

3 BED, 2 BATH

13 APPLIANCES

The kitchen appliance portion of the inspection covers checkpoints involving the observation and operation of the refrigerator, dishwasher, range, trash compactor, garbage disposal, ventilation equipment, microwave and any other permanently installed appliances.

13.1 General Appliance Information

There are no general information points in this section

13.2 Appliance CheckPoints

| Checkpoints | Rating * | Comments |
|--------------|----------|----------|
| Dishwasher | S | |
| Disposal | S | |
| Dryer | MG | |
| Microwave | NA | |
| Oven | NA | |
| Range Hood | NA | |
| Range/Stove | S | |
| Refrigerator | MG | |
| Washer | MG | |
| Other | | |

*Ratings: S=Satisfactory U=Unsatisfactory M=Marginal MG=Missing NA=Not Applicable NV=Not Visible

13.3 Appliance Comments

ALL APPLIANCES WERE POWERED THROUGH THE USE OF A GENERATOR FOR TESTING.

| | |
|-----------------------|----|
| 14 HOA INFORMATION | NA |
| 15 CODE VIOLATIONS | NA |
| 16 PENDING LITIGATION | NA |
| 17 DEMO ORDERS | NA |

18 MOLD DISCLOSURE

Radon Gas and Mold Notice and Release Agreement

**U.S. Department of Housing and Urban Development
Office of Housing
Federal Housing Commissioner**

Property Case#:

492-656498

Property Address:

625 DONLEY DR
EULESS, TX 76039

PURCHASERS ARE HEREBY NOTIFIED AND UNDERSTAND THAT RADON GAS AND SOME MOLDS HAVE THE POTENTIAL TO CAUSE SERIOUS HEALTH PROBLEMS.

Purchase acknowledges and accepts that the HUD-owned property described above (the "Property") is being offered for sale "AS IS" with no representations as to the condition of the property. The Secretary of the U.S. Department of Housing and Urban Development, his/her officers, employees, agents, successors and assigns (the "Seller") and Southwest Alliance of Asset Managers, an independent management and marketing contractor ("M & M Contractor") to the Seller, have no knowledge of radon or mold in, on, or around the Property other than what may have already been described on the web site of the Seller or M & M Contractor or otherwise made available to Purchaser by the Seller or M & M Contractor.

Radon is an invisible and odorless gaseous radioactive element. Mold is general term for visible growth of fungus, whether it is visible directly or is visible when barriers, such as building components (for example, walls) or furnishings (for example, carpets), are removed.

Purchaser represents and warrants that Purchaser has not relied on the accuracy or completeness of any representations that have been made by the Seller and/or M & M Contractor as to the presence of radon or mold and that the Purchases has not relied on the Seller's or M & M Contractor's failure to provide information regarding the presence or effects of any radon or mold found on the Property.

Real Estate Brokers and Agents are not generally qualified to advise purchasers on radon or mold treatment or its health and safety risks. **PURCHASERS ARE ENCOURAGED TO OBTAIN THE SERVICES OF A QUALIFIED AND EXPERIENCED PROFESSIONAL TO CONDUCT INSPECTIONS AND TESTS REGARDING RADON AND MOLD PRIOR TO CLOSING.** Purchases are hereby notified and agree that they are solely responsible for any required remediation and/or resulting damages, including, but not limited to, any effects on health, due to radon or mold in, on or around the property.

In consideration of the sale of the Property to the undersigned Purchases, Purchases does hereby release, indemnify, hold harmless and forever discharge the Seller, as owner of the Property and separately, M & M Contractor, as the independent contractor responsible for maintaining and marketing the Property, and its officers, employees, agents, successors and assigns, from any and all claims, liabilities, or causes of action of any kind that the Purchases may now have or at any time in the future may have against the Seller and/or M & M Contractor resulting from the presence of radon or mold in, on or around the Property.

Purchases has been given the opportunity to review this Release Agreement with Purchases's attorney or other representatives of Purchases's choosing, and hereby acknowledges reading and understanding this Release. Purchases also understands that the promises, representations and warranties made by Purchases in this Release are a material inducement for Seller entering into the contract to sell the Property to Purchases.

Dated this _____ day of _____, 20__.

Purchase's Signature

Purchaser's Signature

Purchase's Printed Name

Purchaser's Printed Name

Form HUD-9548-E (6/2004)

19 ENVIRONMENTAL ISSUES

19.1. Environmental Compliance Record

**ENVIRONMENTAL COMPLIANCE RECORD
SINGLE FAMILY PROPERTY DISPOSITION**

| | | |
|---|---|------------------|
| FHA Case Number: 492-656498 | | |
| Property Address: 625 DONLEY DR., EULESS, TX-76039 | | |
| COMPLIANCE FINDINGS | SOURCE/DOCUMENTATION | |
| <p>1. HISTORIC PRESERVATION</p> <p>Property () is (X) is not listed on the National Register of Historic Places.</p> <p>Property () is (X) is not located in an Historical District.</p> <p>Note: An appropriate deed restriction will be required if property meets either of the foregoing conditions.</p> | <p>http://atlas.thc.state.tx.us/shell-map-address.htm</p> <p>http://atlas.thc.state.tx.us/shell-map-address.htm</p> | |
| <p>2. FLOODPLAIN</p> <p>Property () is (X) is not located within the 100-year Floodplain.(Zones A and V)</p> <p>Note: Flood Insurance may be required.</p> | <p>Panel#: 48439C0230K</p> <p>Map#: 1-X</p> <p>Map Date: 09/25/2009</p> | |
| <p>3. AIRPORT RUNWAY CLEAR ZONES (24 CFR 51D)</p> <p>Property () is (X) is not located within boundary of runway zone.</p> <p>If "yes":</p> <ul style="list-style-type: none"> - Has the airport operator declined to acquire the property? () Yes (X) No - A signed disclaimer is required(24 CFRPart 51D). | <p>INITIAL INSPECTION</p> | |
| <p>4. SUMMARY</p> <p>Additional actions () are (X) are not required on the basis of the findings above. If additional actions are required, describe them in an attachment.</p> | | |
| <p>NOTE: OTHER ENVIRONMENTAL STATUES, EXECUTIVE ORDERS AND AUTHORITIES</p> <p>The remaining statutes and authorities cited at 24 CFR 50.4 do not require compliance because they are not relevant to property disposition actions which do not involve new construction.</p> | | |
| Preparer: JSUDAN | Title: PROPERTY TECH | Date: 01/29/2010 |
| Supervisor: DWILLIAMS | Title: MANAGER | Date: 01/29/2010 |